

# MSR Pocket Rocket Gas Stove

## Potential Fire Hazard

### Limited Product Safety Recall

15 stoves Purchased between 19 Jan 2004 and 9 Feb 2004

If you purchased a MSR Pocket Rocket gas stove between 19 Jan 2004 and 9 Feb 2004 your stove may be one of FIFTEEN with a defect. Please follow these important steps.



- Do not use or attempt to use your MSR Pocket Rocket stove
- Look carefully at the details below to see if your stove is defective, or
- Return the stove to any MSR stove retailer so that they can assess it for you.


#### DEFECTIVE

Batch Number under black rubber seal is **KCL05**.

- **Gold coloured base** AND
- **Hollow Pin**

#### CORRECT

- **Silver OR Gold coloured base**
- **Solid Pin**



If your stove is found to be one of the 15 defective stoves, a replacement stove (without the defect) will be provided to you at no charge.

#### Background Information

Very recently, one of MSR's suppliers made an unauthorized change to the actuator pin of the MSR Pocket Rocket stove. The actuator pin allows the gas to flow out of a gas canister once the stove is attached. The defective actuator pin may lead to a gas leak during installation/removal of the stove to/from the gas canister. In the presence of an ignition source, during installation/removal, there is a possibility of a fire hazard and associated injury.

For further information or to arrange your replacement stove please contact Spelean Pty Ltd. Freecall – 1800 634 853, fax 02 9966 9811, e-mail [msrrecall@spelean.com.au](mailto:msrrecall@spelean.com.au), mail PO Box 645, ARTARMON NSW 1570

See [www.recalls.gov.au](http://www.recalls.gov.au) and [www.spelean.com.au/recalls](http://www.spelean.com.au/recalls)